



Test of 16 1-in PMTs in the pressure vessel with the PMm2 DAQ

Videoconference – Orsay – March 16, 2010

IPNO detector dept.

http://ipnweb.in2p3.fr/~detect

2010/03/16 - Videoconf #1

http://ipnweb.in2p3.fr/~detect B. Genolini



Outline

- 16 1-in PMTs have been tested in the pressure vessel with the PMm2 DAQ, from February 8 to March 8
- When running, we performed at least one acquisition per day, at 1200 V and several DAQ thresholds
- Water leaks occurred
- The failures raise the issue of a necessary slow control
- We performed investigations on the water leaks
- Conclusions for the demonstrator



Preparing the PMTs



- 16 XP3102 1-inch PMTs
- Measured with the FE board + DAQ before potting (pedestals, charge - cf. previous meeting)
- Potting
- Measured before flooding






Routine tests

- High voltage: 1200 V
- Thresholds (DAC channels): 250, 280, 300, 350
- « random » configuration of PARISROC channel gains, common gain at maximum (always the same)
- Gain adjustment, with a target of 1500 ADC channels (to validate the stability of the fitting algorithms)

PN


Counting rate measurement



- The inter-event time is the most reliable
- Measurement on 2 ms maximum due to a software limitation
- Comparison with the number of events over the acquisition time: 50 % dead time!
- Occupancy per 100 ns: non Poissonian




Single electron peak




- Method adopted after several different runs (problems of convergence with some PMTs after the leak due to an increased crosstalk)
- Suppress events where too many coincidences
- Automated fit method: peak detection (ROOT), fit around the peak from an estimated relative width of 30 %



Routine tests: gain






Threshold = 280

- Change for nearly all tubes after the first light leak
- Followed by a slight increase
 - we don't know whether it is caused by the power supply, bias instability due to a slight water leak, or something else




Routine tests: rate




0 100 200 300 400 500 600 700 800

Time (h)

Threshold = 280



Threshold = 350



Fit not always converging

200



Routine test: width

-Th = 280 Th = 300

• Th = 35

--Th = 280 --.Th = 300

--Th = 35


-Th = 280 Th = 300

Th = 35

-Th = 28

-Th = 30

-Th = 35




- Difficulties to fit = peak too large / not enough points
- Rather stable / slight increase, except for PMT#4 and #8



First water leaks

- First detected by an increase of the counting rate, then by an absence of single electron peak.
- First: troubles with the enclosure joint. Replaced.
- Suspected troubles in the pressure vessel's water tighness. Corrected








Second water leaks





- Troubles on PMT#8: high counting rate, high voltage does not go above 800 V (short circuit)
- Short circuit due to the water: burns on the PCB!
- More details in T. Nguyen Trung's memo



Need for a slow control

- Monitor the current (preferably per PMT)
- Monitor the high voltage
- Remote switches on the high voltage, per PMT



Conclusions for the demonstrator

- If no update can be achieved for the frontend board (implementation of a slowcontrol), use the same procedure / code as the one used for the 1-in PMTs
- Make use of a rigid envelope (e.g. with glands) to stabilize the cable potting.