

Mécanique de précision pour les IP-BPM à ATF2

Présentation DEPACC – 12 nov. 2014


Manuel Alvès, Philip Bambade, Oscar Blanco, Frédéric Bogard, Patrick Cornebise,
Jean-Philippe Dugal, Denis Grasset, Bruno Leluan, Bruno Mercier, Jean-Jacques Poher,
Sandry Wallon (LAL)

Laurent Journet (LAPP)

Présentateur : Sandry Wallon


Concevoir et installer un système de positionnement de BPMs à l'IP de ATF2

Un premier critère se détache : réduire la masse



IP Chamber design with 2 extra chambers

Setup of **3 new BPM** in upstream diagnostic zone
(sketch Si-Won JANG – KNU [Korea])



BPMs' expected
resolution : 2 nm

Réduction de la masse



(minimiser les déformations de la table optique)

Utilisation de l'aluminium pour le nouveau système :

- 3 BPMs
- Chambre à vide

Ancien système :

- 2 BPMs en cuivre
- Chambre à vide en inox






Viewports

(interface, limite de responsabilité)


Viewports to be adapted to new
IP chamber → KEK

→ Interfaces clearly defined



New lateral viewport

Fixation chambre / table optique verticale : étude des déformations






Glissement des specs

Positionnement micrométrique

→ Positionnement nanométrique + scanning

- Nouvelle fonction (étude du faisceau par scanning des BPMs)
- Changement d'échelle
 - Changement des solutions positionnement/guidage
(éléments de guidage standards → trépied ; glissière élastique)
 - Dilemme course (230 / 300 μm) vs résolution (2 / 3 nm)

Test actionneurs piezo : course, résolution, tenue au vide, cablage





Test de dégazage des actionneurs :

- PI : OK

- Cedrat : ~ 14 m2 enceinte inox / actionneur !

→ Résolution problème : changement fils et soudure


Complete wiring chain



Qualification des actionneurs : achat d'un interféromètre par le LAL

During approximately 20 hours, the distance between the mirror and the interferometer head is recorded.

The ambient temperature is recorded too.




The 2 curves are similar. This shows the result of dilatation.

Mainly due to the aluminium support.

Interferometer : effect of temperature

To approximate the dilatation effect, focus of the previous curve in the period 21h36 – 31h12 (10 hours approx).



With length of the aluminium support : 280 mm
→ Measured dilatation coefficient = $(-2574+31)E-9/280E-3/(22,24-22,64) = 22E-6 / ^\circ K$


Nb : The theoretical dilatation coefficient for aluminium is $24E-6 / ^\circ K$

Conclusion :


- Interferometer head made of invar (no thermal expansion)
- Temp. probe for software temp. compensation
- But remaining thermal expansion of aluminum vertical bench

PI piezo actuator : interferometer test

(lateral actuator un-mounted)




PI piezo actuator : interferometer test (effect of lateral actuator)




The 3 vertical movers and the lateral mover are installed.
It is the complete configuration for BPM3 move.

With the modification on one hinge




PI piezo actuator : interferometer test

(lateral actuator mounted, elastic hinges and PIs' PID parameters tuned)



Final 3D model & workshop alignment 1




Mires on chamber


Position of internal references were measured with regard of external references (for mires)

→ Data useful for BPMs external pre-alignment


→ Checks performed with 3D Mitutoyo machine (5 μm accuracy, 1 μm resolution)




Vue de droite
Echelle : 1:4




Vue de face
Echelle : 1:4




Vue de gauche
Echelle : 1:4




Vue isométrique
Echelle : 3:20



Coupe A-A
Echelle : 1:4



Coupe B-B
Echelle : 1:4



Coupe C-C
Echelle : 1:4



Final 3D model & workshop alignment 2




Checked BPMs axis with regards of **interfaces** « Chamber / BPMs displacement system »

- Shims placed between actuators and cradles correct BPMs vertical position, roll and pitch angles
- **To be done with actuators running at mid stroke**
- Checks performed with 3D Mitutoyo machine (5 μm accuracy, 1 μm resolution)


3 actuators acting as a tripod for vert. displacement (same for double BPM)



Fabrication (LAPP), contrôles, nettoyage pour vide (UHV)



Test vide : fuite et degazage





Chamber's He leak test OK :

→ Flowrate at 3×10^{-8} Atm.cm³/s
(suitable for UHV)

Data :

- All parts cleaned (SS insert removed and then reinstalled)
- 1.5 mm dia. indium seal (wire)
- Indium wire flatten up to 0.15 mm thickness (screws tightened at 6 Nm)
- Aluminum flanges with 0.7 mm dia. groove for wire positioning
- Test performed at 10^{-5} mbar




Actuators' outgasing OK :

→ Flowrate at 8×10^{-8} mbar.l/s
(suitable for UHV)


(Done at 21 deg. C. and after 100h pumping ; No organic compound detected)



Test final du système de déplacement des BPMs



Shipment, net weight



Chamber (with blank aluminum flanges)

BPMS displacement system

Permanent exportation to KEK (tax to pay)

Chamber's net weight : 27 kg (body : 15 ; Al DN 200 flanges : 2,5x2 ; other Al flanges : 3 ; screws&nuts : 3,2)

BPMS' disp. syst.'s net weight : 4,3 kg

Installation à l'IP



Tests, checks, tunings at KEK



Checking BPM1&2 axis with respect of its cradle references
(can not be done at LAL Orsay due to BPM1&2 activation)

Tests, checks, tunings at KEK




Mounting BPMs
Adjustments w/ positioning tool
(distance to IP plane, lateral alignment,
yaw)




Tests, checks, tunings at KEK



Checking connection w/
feedthrough flanges (→ thin wires
issue to correct)



...many shifts later... : Doublet BPM's misalignment issue



Doublet BPM shown without side cover plate (not allowed configuration with current design)

Cavity A / Cavity B « electrical » misalignment :

- **34 μm shift**
- **2 mrad tilt**


Statically, it's impossible to guarantee to reach (in one shot) a mechanical shift below 10 μm due to stacking tolerances

Idea :

- Clamp right cavity to bench/marble
- Fix red plate to right cavity
- Place left cavity on XZ micrometric stage
- Check tilt&shift with 3D machine
- Adjust position with micrometric stage
- Adjust tilt with surface grinder (tolerance below 0.1 μm)
- Tighten screw when alignment is reached
- Re-check
- Add side cover plates

« Cons » : redesign required

Doublet BPM : Specs understanding



Dimensional specs : $\pm 20 \mu\text{m}$
Positioning specs : $\pm 25 \mu\text{m}$

With a second cavity plus centering pins/holes located at $\pm 1 \mu\text{m}$ (x3) for the doublet BPM, misalignment of BPM A / BPM B could reach more than $50 \mu\text{m}$

Same considerations with parallelism specs would lead to a max tilt angle around 0.4 mrad


Type of aluminum alloy used?
Low thermal expansion, high machinability and stability?

Mechanical references for cavity specifications
Positioning specs

All following drawings : Si-Won JANG, KNU, 09/2011


BPMs – possible improvements (design)

→ Proposition to KNU University - Korea



Change screw heads location to be able to remove side covers (for 3D checks)


Removed material (notch)



4 Notches on side cover enable to access to the cavity reference plane surface (A)


BPMs – possible improvements (3D checking)

→ Proposition to KNU University - Korea



Improved BPMs (KNU re-manufacture)

3D checking and adjustment with LAL's adjustment bench



3D checking of doublet BPM



Adjustment bench for doublet BPM

1. Check tilt & shift of cavityA / cavity B

→ 113 (V) 56 (H) μm (too large)


2. Adjust shift of cavityA / cavity B with dedicated bench

→ 0 (V) 0 (H) μm (or 5 / -5 by using other machine axis system) (OK)



Adjustment bench used with LAL's coordinate measuring machine



Redesign and manufacture of surrounding parts following BPMs re-manufacture




Single BPM with new attachment (no cantilever) → new cradle

Doublet BPM with upstream transition part (to reduce wake field) → new cradle, actuator displaced, new lower part

Cabling improvement




Side view (cross section) of “chamber + BPMs displacement system”



Installation du nouveau système



Installation du nouveau système




Installation du nouveau système : alignement




Traitement statistique (20 mesures)
→ Erreur alignement $8 \mu\text{m}$ / SD 12 à $20 \mu\text{m}$

Installation du nouveau système : mesures alignement vertical in situ – actuateurs on



**Traitement statistique (20 mesures)
→ Erreur alignement 40 μm (à vérifier)**

Installation du nouveau système : mesures et alignement lateral in situ (lateral) – actuateurs on



Conclusion

- Alignement dans la course des actionneurs
- Course restante disponible pour scanning faisceau
- Equipement installé à l'IP – vide OK
- Faisceau remis en marche cette semaine...

... Aparté sur la feuille vierge